
SERVICE PARTS LIST

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS REVISEDBULLETIN DATE Feb. 2003 **CHARGER** WIRING INSTRUCTION 48-59-0255 A28A or 976D CATALOG NO.



6,8

Insert strain relief as shown with the flat side of the strain relief positioned against the inside wall of the charger housing.

MILWAUKEE ELECTRIC TOOL CORPORATION

crossover prior to installation of strain relief into top housing.

Cord set to be free from conductor twists and cord