

## **SERVICE PARTS LIST**

## **BULLETIN NO.** 54-04-2330

SPECIFY CATA	LOG NO. AND SERI	REVISED BULLETIN	DATE		
HEATE	D GEAR FLA	WIDING INCTDI	Sept. 2023		
CATALOG NO.	48-11-2330	SERIAL NO.	P07A	- WIRING INSTRU	ICTION




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.	FIG.	NOTES
1	12-20-0807	Service Nameplate	(1)	1	A clean,
2	42-44-1211	USB-C Cord	(1)		adhesive

A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.