




# Operating Instructions and Parts Manual

## 12 x 21-inch, 6-Speed Wood Lathe


Model JWL-1221SP



**JET**  
427 New Sanford Road  
LaVergne, Tennessee 37086  
Ph.: 800-274-6848  
[www.jettools.com](http://www.jettools.com)

**Part No. M-719115**  
Edition 1 06/2018  
Copyright © 2018 JET

### 15.1.1 JWL-1221SP Bed Assembly – Exploded View




## 15.1.2 JWL-1221SP Bed Assembly – Parts List

<b>Index No</b>	<b>Part No</b>	<b>Description</b>	<b>Size</b>	<b>Qty</b>
1	JWL1221VS-201	Tool Caddy .....		2
2	TS-0255021	Socket Head Button Screw.....	5/16"-18x1/2"	4
3	TS-0207071	Socket Head Cap Screw .....	1/4"-20x1-1/4"	4
4	TS-0720071	Lock Washer.....	1/4"	4
5	TS-1490021	Hex Cap Screw.....	M8x16	1
6	6295717	Knob .....		1
7	JWL1221VS-207	Motor Pulley Access Door .....		1
8	TS-081C022	Pan Head Screw.....	#10-24X3/8"	3
9	JWL1221VS-209	Magnet.....		1
10	JWL1221VS-210	Bed .....		1
11	JWL1221VS-211	Warning Label .....		1
	JWL1221VS-TBA	Toolrest Base Assembly ( <i>includes #12 thru #19</i> ) .....		1
12	JML-59A	Lock Handle Assembly .....	5/16"-18x5/8"	1
13	JWL1221VS-213	Toolrest Base.....		1
14	JWL1221VS-214	Rubber Cover .....		1
15	JWL1221VS-215	Eccentric Rod .....		1
16	JWL1221VS-216	Toolrest Clamp Bolt .....		1
17	JML-44	Clamp .....		2
18	JML-81	Hex Nut.....		2
19	JML-49	C-Ring.....	STW-12	1
20	JWL1220-142	Toolrest.....	6"	1
21	JWL1220-142A	Toolrest.....	10"	1
	JWL1221VS-TA	Tailstock Assembly ( <i>includes # 17, 18, 22 thru #34</i> ) .....		1
	JWL1221VS-THA	Tailstock Handwheel Assembly ( <i>includes #22 thru #24</i> ) .....		1
22	JWL1221VS-222	Handle .....		1
23	JWL1221VS-223	Handwheel .....		1
24	TS-0267021	Set Screw .....	1/4"-20x1/4"	2
25	JML-45A	Lock Handle Assembly, Tailstock .....	5/16"-18x3/4"	1
26	JWL1221VS-115	Socket Head Button Screw.....	#10-32x5/8"	1
27	JWL1221VS-227	Key.....		1
28	JML-58	Eccentric Rod, Tailstock .....		1
29	JWL1221VS-229	Rubber Cover .....		1
30	JWL1221VS-230	Lead Screw.....		1
31	JWL1221VS-231	Quill.....		1
32	JML-63	C-Ring.....	STW-10	1
33	JWL1221VS-233	Tailstock Clamp Bolt.....		1
34	JWL1221VS-234	Tailstock.....		1
35	708331	Live Center Assembly ( <i>includes #36 thru #39</i> ) .....		1
36	JML-52	Live Center Head.....		1
37	JML-52A	Center Point for Live Center .....		1
38	BB-6002ZZ	Ball Bearing .....	6002ZZ	1
39	JML-54	Live Center Shaft.....		1
40	JWL1221SP-240	Motor Pulley .....	6-step	1
41	6295796	Nylon Insert Socket Set Screw .....	1/4"-20x3/8"	2
42	TS-0640081	Nylon Nut .....	5/16"-18	2
43	JWL1221SP-243	Motor Plate .....		1
44	JWL1221VS-244	Spring .....	69L	1
45	JWL1221VS-245	Ratchet Key .....		1
46	TS-0051061	Hex Cap Screw.....	5/16"-18x1-1/4"	2
47	JWL1221VS-247	Rack.....		1
48	TS-081C011	Pan Head Screw.....	#10-24x1/4"	2
49	JWL1221VS-249	Hock .....		1
50	TS-0680031	Flat Washer .....	5/16"	1
51	JWL1221SP-251	Motor.....	3/4HP 1PH 115V	1
52	JWL1221SP-252	Motor Label.....		1
	JWL1221SP-251MF	Motor Fan .....		1
	JWL1221SP-251MFC	Motor Fan Cover.....		1
	JWL1221SP-251RC	Running Capacitor .....	40mF 250VAC	1
	JWL1221SP-251RCC	Running Capacitor Cover .....		1

<b>Index No</b>	<b>Part No</b>	<b>Description</b>	<b>Size</b>	<b>Qty</b>
66 .....	JWL1221VS-266 .....	Rubber Cover .....	.....	1
67 .....	TS-0560071 .....	Hex Nut.....	#10-24.....	1
68 .....	JML-11 .....	Knockout Rod .....	.....	1
71 .....	JET-92.....	JET Logo with 3M Adhesive .....	92x38mm .....	1
72 .....	TS-081C072.....	Pan Head Screw.....	#10-24x1-14" .....	2
73 .....	JWL1221SP-273.....	ID Label .....	.....	1
74 .....	TS-0253031 .....	Socket Head Button Screw.....	#10-24x1/2" .....	2
76 .....	JWL1221VS-276 .....	Clamp .....	1/2" .....	2
78 .....	TS-0254021 .....	Socket Head Button Screw.....	1/4-20 x 1/2" .....	2
79 .....	JWL1221SP-279 .....	Spring .....	48L.....	1


### 15.2.1 JWL-1221SP Headstock Assembly – Exploded View



## 15.2.2 JWL-1221SP Headstock Assembly – Parts List

<b>Index No</b>	<b>Part No</b>	<b>Description</b>	<b>Size</b>	<b>Qty</b>
.....	JWL1221SP-HA	Headstock Assembly ( <i>includes #4 thru #34</i> )		1
1	JML-2	Faceplate	3"	1
3	JML-3	Spur Center	MT2	1
3A	JML-3A	Center Point for Spur Center		1
4	TS-0253031	Socket Head Button Screw	#10-24X1/2"	3
5	JWL1221VS-105A	Cover		1
6	JWL1221VS-106A	Spindle	1"-8TPI	1
7	JML-5	Key	5x5x25mm	1
8	BB-6005VV	Ball Bearing	6005VV	1
11	JWL1221VS-111	Headstock Casting		1
16	JWL1221SP-116	V-Belt	310J-4	1
17	JWL1221SP-117	Spindle Pulley	6-step	1
18	6295710	C-ring	S-25	1
19	JML1014-188	Spring		1
20	JWL1221VS-120	Pan Head Screw	M3x35	1
21	JML1014-189	Index Pin		1
22	BB-6004VV	Ball Bearing	6004VV	1
23	JWL1221VS-123	Handwheel		1
24	TS-0267021	Set Screw	1/4"-20x1/4"	2
25	JWL1221VS-125	Pulley Access Door		1
26	JWL1221SP-126	Speed Label		1
27	TS-0267041	Set Screw	1/4"-20x3/8"	2
28	JWL1221VS-128	Pan Head Screw	M3x50	1
29	4224B-179	Nylon Nut	M3	2
31	JWL1221VS-131A	Spindle Lock Pin		1
32	JWL1221VS-132	Spring		1
33	JML1014-187	C-Ring	STW-9	1
34	JWL1221VS-134	Spring		1

### 15.3.1 JWL-1221SP Switch Box Assembly – Exploded View



### 15.3.2 JWL-1221SP Switch Box Assembly – Parts List

Index No	Part No	Description	Size	Qty
	JWL1221SP-SBA.....	Switch Box Assembly ( <i>includes #1 thru #15</i> ) .....		1
1	JWL1221SP-301 .....	Switch Box (includes #1, 4, 14, 15) .....		1
2	JWL1221VS-302 .....	Tapping Screw.....	M3x19mm .....	2
3	JML-65 .....	Main Switch .....		1
4	JWL1221SP-304 .....	Control Panel Label .....		1
5	JWL1221VS-320 .....	Strain Relief .....	6P-4 .....	2
6	JWL1015-170.....	Power Cable .....		1
7	JWL1221SP-307 .....	Phillips Pan Hd Tapping Screw .....	M3.5x 8mm .....	4
8	JWL1015-171 .....	Ground Plate .....		1
9	JWL1015-163.....	Tapping Screw.....	M3.5x6mm .....	1
10	TS-073304 .....	External Tooth Lock Washer .....	1/4" .....	2
11	TS-1533032 .....	Pan Head Screw.....	M5x10 .....	2
12	JWL1221SP-312 .....	Dust Sheet (not shown) .....		2
13	TS-081C072 .....	Pan Head Screw .....	#10-24x1-14" .....	2
14	F009669 .....	Socket Head Button Screw.....	#10-24x3/8" .....	2
15	TS-0560071 .....	Hex Nut.....	#10-24.....	2