



BOSCH

Reciprocating saw

GSA 120 | 3 601 FB1 080

Table of Content

Spare parts list.....	2
Illustration - Type.....	4

Spare parts list

Item	Part Number	Description
2	1 604 220 53J	Field
3	1 604 010 B7E	Armature
4	1 607 200 358	Switch
5	1 604 460 225	Power supply cord CN 2,65m 2 x 1,5mm H07 RN-F
6	2 600 703 017	Grommet Ø6,4-Ø7,2x76 MM
7	1 619 P06 313	Cable Clip
9	1 619 P15 154	Manufacturer's nameplate GSA 120
13	1 619 P00 456	Ball Bearing 7x19x6 MM
14	1 619 P10 481	Ball Bearing
19	2 603 490 023	Torx Oval-Head Screw 4x20
22	1 619 P13 893	Insulating Sleeve
23	1 619 P06 227	Rubber Ring
28	2 600 914 017	Needle bearing Ø6/12 MM
29	1 619 P13 916	Thrust Ring
30	1 619 P13 910	Cover Plate
31	1 619 P14 211	Cover Plate
32	1 619 P13 911	Lifting Rod
33	1 619 P13 907	Bushing
34	1 619 P14 546	Shim
35	1 619 P13 896	Set Of Handles
36	F 000 640 007	O-Ring
37	1 619 P14 673	Air-Deflector Ring
38	1 619 P14 201	Protective Cover
39	1 619 P14 202	Supporting foot
40	1 619 P14 206	Plate
41	1 619 P14 207	Cover
42	1 619 P14 196	Plate
43	1 619 P14 424	Quick-Clamping Device
44	1 619 P06 286	Insulating Cap
49	2 916 683 006	Spring Lock Washer DIN 127-B 5
50	1 619 P11 432	Hex Socket Head Cap Screw
51	1 613 435 014	Torx Oval-Head Screw M5x16-TORX,T25 SILVER
52	1 619 P01 678	Screw
53	2 603 490 022	Screw 4x16

Spare parts list

Item	Part Number	Description
54	1 619 X00 658	Screw
55	1 619 P01 508	Screw
56	1 619 P07 060	Connecting Cable
57	1 619 P14 209	Connecting Cable
58	1 619 P14 210	Connecting Cable
59	1 619 P11 420	Hexagon Socket Wrench
801	1 619 P15 313	Motor Housing
808	1 619 P15 144	Nameplate
810	1 619 P10 063	Carbon-Brush Set
824	1 619 P15 315	Gear Housing
826	1 619 P15 317	Bevel Gear Set
895	3 605 430 003	Grease Tube Albida

Illustration - Type - E

3 601 FB1 080
 Issue | 19-04-26
 Stand | Fig./Abb. 1

