



**BOSCH**

# Percussion Drill

GSB 20-2 | 3 601 AA2 080

---

## Table of Content

Spare parts list.....	2
Illustration - Type.....	4

**Percussion Drill | GSB 20-2 | 3 601 AA2 080**

**Spare parts list**

<b>Item</b>	<b>Part Number</b>	<b>Description</b>	
1	2 609 101 797	Motor Housing	
2	2 609 120 463	Field	
4	1 607 200 508	On-Off Switch	BLACK
5	2 604 460 245	Power supply cord 0,75mm H05 VV-F	CN 220V 2,65m 2 x
6	2 600 707 059	Grommet	Ø6,9 MM
13	1 900 905 020	groove ball bearing	DIN 625 627-2Z/C3
14	1 900 905 021	groove ball bearing	9x24x7
15/25	2 604 616 006	Compression Spring	
15/28	2 609 100 939	Knob	
15/29	2 609 111 330	Control Shaft	
15/30	2 600 590 006	Ratchet Cap	
15/31	2 916 080 912	Locking Washer	
15/32	1 903 230 010	Ball	DIN 5401-5,5MM-III-ST
15/34	2 609 111 487	Shim	
15/48	2 600 101 047	Shim	0,3 MM
15/49	2 600 550 008	Disc Spring	
15/52	2 609 111 907	Adjusting Slide	
15/53	2 609 111 220	Slide Pin	
15/54	2 609 101 436	Holding Plate	
15/55	2 609 101 419	Rotary Knob	
15/56	2 600 206 025	O-Ring	
15/57	2 609 111 893	Link Guide	
15/58	2 604 651 026	Coiled Spring	
16	2 609 199 438	Brush Plate	
33	2 609 111 383	Headless Screw	
40	2 910 611 002	Tapping Screw	DIN 7981-ST2,2x9,5-C-H
57	2 603 490 022	Screw	4x16
58	2 601 035 001	Cable Clip	
652	2 609 199 430	Auxiliary Handle	
653	2 603 001 009	Depth-Gauge	
803	2 609 199 451	Armature set	230-240V
810	1 617 000 525	Carbon-Brush Set	
817	1 608 571 080	Key Chuck	Ø1,5-13 MM
818	2 609 199 446	Drilling Spindle	

Spare parts list

Item	Part Number	Description
819	2 609 199 450	Gear Housing
827	2 609 199 449	Bearing Flange
835	2 609 199 447	Transmission
860	2 607 950 007	Chuck Wrench SG2

Illustration - Type - E

3 601 AA2 080  
 Stand } 34-10  
 Issue } 15-05-18

Fig. /Abb. 1

