



BOSCH

Percussion Drill

GSB 20-2 RE | 3 601 AA2 180

Table of Content

Spare parts list.....	2
Illustration - Type.....	4

Percussion Drill | GSB 20-2 RE | 3 601 AA2 180

Spare parts list

Item	Part Number	Description
1	2 609 100 936	Motor Housing
2	2 609 120 463	Field
4	1 607 200 270	Switch BLACK
5	2 604 460 245	Power supply cord CN 220V 2,65m 2 x 0,75mm H05 VV-F
6	2 600 707 059	Grommet Ø6,9 MM
13	1 900 905 020	groove ball bearing DIN 625 627-2Z/C3
14	1 900 905 021	groove ball bearing 9x24x7
15/25	2 604 616 006	Compression Spring
15/28	2 609 100 939	Knob
15/29	2 609 111 330	Control Shaft
15/30	2 600 590 006	Ratchet Cap
15/31	2 916 080 912	Locking Washer
15/32	1 903 230 010	Ball DIN 5401-5,5MM-III-ST
15/34	2 609 111 487	Shim
15/48	2 600 101 047	Shim 0,3 MM
15/49	2 600 550 008	Disc Spring
15/52	2 609 111 907	Adjusting Slide
15/53	2 609 111 220	Slide Pin
15/54	2 609 101 436	Holding Plate
15/55	2 609 101 419	Rotary Knob
15/56	2 600 206 025	O-Ring
15/57	2 609 111 893	Link Guide
15/58	2 604 651 026	Coiled Spring
16	2 609 199 439	Brush Plate
33	2 609 111 383	Headless Screw
40	2 910 611 002	Tapping Screw DIN 7981-ST2,2x9,5-C-H
57	2 603 490 022	Screw 4x16
58	2 601 035 001	Cable Clip
652	2 609 199 430	Auxiliary Handle
653	2 603 001 009	Depth-Gauge
803	2 609 199 451	Armature set 230-240V
810	1 617 000 525	Carbon-Brush Set
817	1 608 571 080	Key Chuck Ø1,5-13 MM
818	2 609 199 446	Drilling Spindle

Spare parts list

Item	Part Number	Description
819	2 609 199 450	Gear Housing
827	2 609 199 449	Bearing Flange
835	2 609 199 447	Transmission
860	2 607 950 007	Chuck Wrench SG2

Illustration - Type - E

