



Position	Amount	Type number	Description
1	1	399999990	Part not needed
3	1	341603640	Drill spindle
4	1	341511630	Depth stop
5	3	141122490	Self-tap. fill. h. screw
6	1	316030990	Gear housing cpl.
7	1	340004010	Sliding block
8	1	316027710	Switch housing compl.
9	1	316030370	Intermediate gear
10	1	341540010	Guide bolt
11	1	339129270	Shift fork
12	1	344095910	SEAL
13	1	316031000	Gear flange cpl.
14	1	339210830	Shaft sealing ring
15	1	141181680	Retaining ring
16	1	143110220	BALL BEARING, 15x32x9
17	1	341055650	Slotted disc
18	1	316029530	Control knob cpl.
20	1	343376040	Sealing ring
21	1	344095920	Rubber buffer
22	1	143113400	Ball bearing, 8x22x7
23	1	310008130	Armature cpl. 120 V
24	1	143114750	Ball bearing, 6X 19X 6
25	1	343374270	Intermediate flange
26	1	314000770	Support handle compl.
27	1	338041750	Rating plate
28	1	343077960	Electronic unit
29	1	343406880	poti switch 230V
30	5	141117060	Self-tap. fill. h. screw
31	1	343393030	Drill Handle w/overmold green
32	1	343362490	Cable clip
34	1	143192430	O-ring
35	2	141118260	Self-tap. fill. h. screw
36	1	311009840	Field coil 120V
37	1	315012650	Motor housing
38	1	338115540	Metabo label
39	2	338115410	Indication label
40	1	316032020	Brush holder module 120V
41	1	344494030	Cable with UI-CSA-plug
43	1	344101160	Cable sleeve
44	1	316034550	Brush set 230V/120V
45	1	141155810	Ring

46	2	344092220	Rubber plug
47	1	338115880	Warning label
48	1	316035730	Fan w. prot. Grid
880	1	344130930	Grease 50Gr 1,8oz
882	1	344130970	Grease 50Gr 1,8oz
1001	1	338502450	Diagram

