

WIRING PROCEDURE:

- a.) Wire (Item No. 10) Push on terminals as shown.
- b.) Wires No. 1, 2, 3, & 4 Push on terminals on back of switch (Item No. 2)
- (Terminals are identified on back of switch.) c.) Red, black & white wires from receptacle (Item No. 7) – Push on
- correct terminals on back of switch (Item No. 2).
- d.) Blue wire from receptacle (Item No. 7) Push on terminal as shown.
- e.) Black wires from lamp (Item No. 5) Push on terminals marked
- "Lamp" on back of control module (Item No. 1).