

00 _ Component Parts (Small #) Are Included When Ordering The Assembly (Large #).




FIG. PART NO. 1 12-20-2591 DESCRIPTION OF PART

Service Nameplate (Not Shown)

NO. REQ. (1) FIG. NOTES

1

A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.