


# SERVICE PARTS LIST

SPECIFY CATAL	DG NO. AND SERIA	REVISED BULLETIN	DATE			
M28 BATTERY				54-04-7011	Nov. 2010	
CATALOG NO.	48-11-2830	SERIAL NUMBER	C71F	WIRING INSTR	ING INSTRUCTION	

## EXAMPLE:



Component Parts (Small #) Are Included When Ordering The Assembly (Large #).



#### FIG. PART NO.

### DESCRIPTION OF PART

- 1 10-20-4550 Fu
- Fuel Gauge Label (Front of tool)
- 2 12-20-2900 Service Nameplate (Bottom of tool) (1)

#### FIG. NOTES

NO. REQ.

(1)

1, 2 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or name plate.