
## SERVICE PARTS LIST



(2)

(4)

(12)

(1)

(1)

(3)

42

10-20-0895

3 x 12 Hex Drive Screw

Service Nameplate

Logo Label

M6 x 19 Hex Drive Screw

3.0 x 15 Washer Hd. Hex Drive Scr.

Charger Board Assembly (Incl. #40)

6

8

9

10

11

05-88-0925

05-88-1000

05-88-0760

10-20-2990


12-20-1555

22-09-0820

MILWAUKEE ELECTRIC TOOL CORPORATION 13135 W. LISBON RD., BROOKFIELD, WI 53005

Terminal Warning Label

(3)



WIRING SPECIFICATIONS			
Wire No.	Wire Color	Origin or Part No.	Terminals, Connectors and End Wire Preparation
1	Black	22-64-1080	Component of the cord set. Connect to J1-1 on Bay 3.
2	White	22-64-1080	Component of the cord set. Connect to J2-2 on Bay 3.
3	White	23-94-1210	Component of the leadwire assembly. Connect to J2-1 on Bay 3 / Connect to J2-2 on Bay 2.
4	Black	23-94-1315	Component of the leadwire assembly. Connect to J1-2 on Bay 3 / Connect to J1-1 on Bay 2.
5	White	23-94-1210	Component of the leadwire assembly. Connect to J2-1 on Bay 2 / Connect to J2-2 on Bay 1.
6	Black	23-94-1315	Component of the leadwire assembly. Connect to J1-2 on Bay 2 / Connect to J1-1 on Bay 1.
7	Red	23-74-1525	Component of the battery connector assembly. 3 assemblies. Connect to J3 on corresponding Bays 1, 2 and 3.
8	White	23-74-1525	Component of the battery connector assembly. 3 assemblies. Connect to J5 on corresponding Bays 1, 2 and 3.
9	Black	23-74-1525	Component of the battery connector assembly. 3 assemblies. Connect to J4 on corresponding Bays 1, 2 and 3.
10	Red	23-28-0135	Component of the LED/Lens. 3 assemblies. Service according to the instructions above.
11	White	23-28-0135	Component of the LED/Lens. 3 assemblies. Service according to the instructions above.
12	Green	23-28-0135	Component of the LED/Lens. 3 assemblies. Service according to the instructions above.
BULK LEAD WIRE - BULLETIN 58-01-0003			