

No. 49-16-2741

Bristle Brush Attachment

Serial No. M93A

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
10	-----	Gearbox	(1)
11	05-78-0029	M5 x 8mm Pan Hd. T-25 Machine Screw	(1)
12	05-74-0315	M5 x 17mm Pan Hd. T-25 Machine Screw	(2)
13	42-76-0053	Collar	(1)
14	05-88-0051	M6 x 30mm Cap Hd. Hex Recess Mach. Scr.	(1)
15	05-55-0052	10mm M6 Hex Nut	(1)
16	-----	Shield	(1)
17	06-65-0121	'L' Pin	(2)
18	06-65-0122	Hair Pin Cotter Pin	(2)
19	42-12-0026	Output Shaft Axle	(2)
25	14-46-0349	Bristle Brush Assembly (Set of 1)	(2)
26	-----	Drive Shaft (Bristle Brush)	(1)
27	42-38-0036	Shield Assembly	(1)
28	14-29-0024	Gearbox Assembly	(1)
29	12-20-0511	Service Nameplate (Not Shown)	(1)
30	10-20-8997	Long Warning Label-Bristle Brush (Not Shown)	(1)
31	38-50-0097	Drive Shaft Assembly (Bristle Brush)	(1)
32	49-96-0012	5mm Hex Key	(1)

