



1/2" Pneumatic Impact Wrench

#505102, JAT-102



Operation & Parts Manual

M-505102

Edition 3

11/2018




Stock No.:
Serial No.:
Purchased from:
Date purchased:

JET
427 New Sanford Road
LaVergne, TN 37086
Ph.: 800-274-6848
www.jettools.com

Copyright © 2015 JET

#505102, JAT-102, 1/2-inch Impact Wrench – exploded view



#505102, JAT-102, 1/2-inch Impact Wrench – parts list

Index	Part No.	Description	Qty
1	JAT102-01	Motor housing	1
2	40302	Anvil 1/2in.	1
3	40303	Socket retainer	1
4	40304	Trigger	1
5	40305	O-Ring 6.5x2mm	1
6	40306	Anvil bushing	1
7	40307	Hammer dog	1
8	40308	Hammer cage	1
9	JAT102-09	Screw M3x8L	2
10	40310	Hammer pin 8x52.6L	1
11	40311	Drive cam	1
12	40312	Screw M8x8L	1
13	BB-6001VV	Ball bearing 6001	2
14	40314	Rear end plate	1
15	40315	Rotor	1
16	40316	Rotor vane	6
17	40317-13	Spring pin 3x12L	2
18	40318	Cylinder	1
19	40319A	Front end plate	1
21	JAT102-21	Rear cover	1
22	40322	Rear gasket	1

Index	Part No.	Description	Qty
23	40323	Exhaust deflector	1
25	40325	Reverse valve	1
26	40326	Valve seat	1
27	40327	Valve stem	1
28	SB-3/8	Steel ball 3/8in.	1
29	40329	Spring	1
31	40331	Air inlet	1
32	40332	Air regulator	1
33	40333	O-Ring 8x2	1
34	40329-12	Spring	1
35	40335	Rubber collar	1
37	40337	Spring pin 3x18L	1
38	40334A	Screw M5x7L	1
39	40339	Nose guard	1
40	40340	Screw M5x5L	1
41	40341	Spring	1
42	40342	Pin	1
43	40343	Screw M5x16L	4
44	TS-2361051	Spring washer M5	4
45	AH-3X	Spring pin 3x16L	1

JAT102-RPK Repair Kit, contains 3,5,16(6),33

JAT102-RBK Rebuild Kit, contains 2,10,14,17(2),18,19,45