



OWNER'S MANUAL AFS-1000B Air Filtration




JET EQUIPMENT & TOOLS, INC.
A WMH Company
www.jettools.com

P.O. BOX 1349
Auburn, WA 98071-1349
e-mail jet@jettools.com

253-351-6000
Fax 800-274-6840
M-708620 5/01

Parts Breakdown



Parts List for the AFS-1000B Air Filtration

Index No.	Part No.	Description	Size	Qty.
1	708731	Filter		1
2	708733	Filter Bag		1
4	AB001008	Door Clip Set		2
5	AB001108W	Air Box		1
6	SJ069300	Pan Head Bolt	M6x12	6
7	OO1033	Switch Wire w/Terminal		1
8	NH050800	Nut	M5	2
9	WE050000	Star Washer	M5	2
10	OO1022W	Switch Plate		1
	AB001022W	Switch Plate Set (assembly not shown)		
11	SP059300	Pan Head Bolt	M5x12	1
12	IC001015	Electric Wire		1
13	998623	Strain Relief		1
14	330075	5A Thermos Switch		1
15	10042	Nut	M6	4
16	330006	Sleeve		4
17	330005	Spacer		4
20	WF061310	Flat Washer	M6	6
21	ST049200	Tapping Screw	M4x8	2
22	SR089400	Hex Socket Bolt	M8x16	1
23	OO1055	Fan Blade		1
24	OO1056	Fan Housing		1
25	OO1057	Motor		1
	CA001000B	Capacitor (not shown)		1
26	NF050800	Nut	M5	4
28	708711	Remote Control		1
29	330004	Flange		1
30	330043	PC Board		1
31	OO1023	Eye Bolt		4
32	NH061000	Nut	M6	4
33	SN490200	Counter Sunk Bolt	1/8"x1/4"	3
34	SP049100	Pan Head Bolt	M4x6	4
35	OO1029	Concave Handle		2
36	SR060600	Hex Socket Bolt	M6x30	4
37	WF061620	Washer	M6x16	8
38	LM000513	I.D. Label		1
39	LM000344	Remote Label		1
40	990638	Wiring Nut	P2	1
41	SF069200	Rivet Nut	M6x8	4
42	330074	Pad		4
43	WS060000	Spring Washer	M6	6
44	OO1027	Hanger Plate		4
45	SH069200	Hex Head Bolt	M6x8	8
46	WS060000	Spring Washer	M6	8
	OO1045	Color Stripe (not shown)		1
	AH001103	Hardware Kit (not shown)		1
	LM000280	JET Air Filtration I.D. Label (not shown: side of cabinet)		2
	LM000210	Warning Label		1

Replacement Filters:

708733	Inner Filter
708731	Electrostatic Filter
708734	Charcoal Filter
708732	Washable Electrostatic Filter