



Position	Amount	Type number	Description	PG
1	1	316043680	Handle half compl.	19
2	1	342022140	Torsion spring	11
3	1	316042960	Screw set	22
4	1	343394670	Switch lock	11
5	1	343408770	Switch,120V	21
6	1	344098340	Switch guard	11
7	1	338049710	NAME PLATE	11
9	1	311010890	Field coil assembly w.field coil,120V	36
10	1	143114860	Ball bearing ,	22
11	1	343394600	Baffle	11
12	1	344098370	Rubber ring	11
13	1	310009350	Armature compl. 120V	37
14	1	344098350	Cable sleeve,230V	26
15	1	344098360	Cable sleeve,120V	11
16	1	344098380	Rubber plug	11
17	1	143115100	Ball bearing, 15X 35X 11	19
18	1	399999990	Part not needed	
19	1	316043690	Handle compl.	14
21	1	315416390	Motor bracket	31
22	1	143114040	Ball bearing, 10x26x8	22
23	1	341147850	Key	11
25	1	341201020	Gear wheel	22
26	1	344098320	Ring	11
27	1	315416380	Gear box cover	14
28	1	143110460	Ball bearing, 17x40x12	25
29	1	341005750	Spacer sleeve	11
31	1	341005760	Spacer sleeve	13
32	1	141180110	Retaining ring	12
33	2	341031980	Flange	18
34	1	341012990	Supporting disc	11
35	1	339203110	Wheel guard compl.	33
36	1	341032010	Flange protection	11
37	1	343394620	Motor housing cover	15
39	2	343000940	Cover cap for Kohlebuersten	11
40	1	316042980	Carbon brush set,120V	19
41	2	343000930	Brush holder	17
42	1	343394610	Motor housing	25
43	1	341515330	Connector bolt	14
44	1	343394570	Stop gauge	20
48	1	316043700	Locking bolt compl.	13
54	1	316043720	Spindle stop compl.	11

Position	Amount	Type number	Description	PG
56	2	338121160	Metabo label	11
57	1	342050850	Spring	18
58	1	341520180	Bolt	16
59	1	343395160	Cable clip	11
60	1	344098330	Cable sleeve	11
63	1	339160780	GUARD PLATE	16
65	1	344497530	Cable w.UL/CSA-plug	27
66	1	338121170	Indication label	11
69	1	341147840	Spindle	19
70	1	339133390	Clamping Jaws	20
71	1	343394580	Threaded spindle holder	16
72	1	339133420	steelplate	11
74	1	341515360	Depth stop	16
75	3	344098280	Rubber foot	11
76	1	339133410	Base table	32
77	1	344163520	Spanner Kentool	13
78	1	343394890	Dummy plug	11
79	1	399999990	Part not needed	
80	1	399999990	Part not needed	
81	1	399999990	Part not needed	
82	1	316043800	Spindle compl.	30
83	3	344098550	Rubber plug	12
84	1	143195240	Gasket	11
880	1	344131180	Grease Tube	11
1001	1	338504540	Wiring diagram, 120V	

