



BOSCH

Drill

GBM 13 RE | 3 601 D77 580

Table of Content

Spare parts list.....	2
Illustration - Type.....	3

Spare parts list

Item	Part Number	Description
1	2 609 100 574	Motor Housing BLUE
2	2 604 220 718	Field 230V
4	2 607 200 623	Switch
5	2 604 460 245	Power supply cord CN 220V 2,65m 2 x 0,75mm H05 VV-F
6	2 600 707 059	Grommet Ø6,9 MM
7	2 601 035 001	Cable Clip
13	2 609 110 153	Ball Bearing 8x22x7
14	2 609 110 491	Ball Bearing
16	2 609 120 356	Brush Plate
19	2 603 490 022	Screw 4x16
25	2 609 100 618	Reversing Switch
29	1 900 210 000	O-Ring 5,0x1,5 MM
33	2 609 110 719	Ball Bearing
34	2 609 199 158	Bearing Bracket
43	2 609 110 709	Cylindrical Gear
803	2 609 120 339	Armature set 220-240V
810	2 610 391 290	Carbon-Brush Set
841	2 609 120 407	Spindle Assembly
846	1 608 571 080	Key Chuck Ø1,5-13 MM
847	2 607 950 007	Chuck Wrench SG2

Illustration - Type - E

3 601 D77 580
 Stand | 12-08
 Issue | 15-05-13

Fig./Abb. 1

