



**BOSCH**

# Drill

GBM 6 RE | 3 601 D72 581

---

## Table of Content

Spare parts list.....	2
Illustration - Type.....	3

## Spare parts list

Item	Part Number	Description
1	2 609 100 741	Housing
2	2 609 120 279	Field 230V
4	2 607 200 623	Switch
5	2 604 460 245	Power supply cord CN 220V 2,65m 2 x 0,75mm H05 VV-F
6	2 600 707 062	Grommet Ø7x8,4 MM
13	2 609 110 745	Ball Bearing
14	2 609 110 491	Ball Bearing
16	2 609 120 356	Brush Plate
19	2 603 490 022	Screw 4x16
25	2 609 100 618	Reversing Switch
34	2 609 199 157	Bearing Bracket
46	2 608 571 009	Chuck Ø1-6,5 MM, 3/8"
803	2 609 120 337	Armature set 230-240V
810	2 610 391 290	Carbon-Brush Set
841	2 609 120 405	Spindle Assembly

Illustration - Type - E

3 601 D72 581

Stand | 14-01-09  
Issue | 14-01-30

Fig. /Abb. 1

