



BOSCH

Portable Metal Shears

PS 70 | 3 601 J26 110

Table of Content

Spare parts list.....	2
Illustration - Type.....	4

Spare parts list

Item	Part Number	Description			Illustration
1/17/21	1 600 102 029	Washer	1,0 MM	THICK	1
1/17/22	1 606 337 004	Ring Gear			1
1/17/23	1 606 337 003	Planet Gear			1
1/17/27	3 600 102 049	Shim ring			1
1/17/28	3 602 311 052	U-Sheet			1
1/17/29	3 600 905 158	Track-Supporting Roller			1
1/17/30	1 600 900 038	Ball Bearing	626 DIN 625		1
1/17/31	1 605 190 266	Gear Housing			1
1/17/32	3 602 317 042	Tappet			1
1/17/33	2 910 401 118	Hex Socket Head Cap Screw		DIN 912-M4x8-12.9	1
1/17/34	3 608 635 009	Knife			1
1/17/35	3 602 311 047	Plain Washer	0,2 mm		1
1/17/35	3 602 311 048	Plain Washer	0,4mm		1
1/17/35	3 602 311 049	Plain Washer	0,6mm		1
1/17/36	3 606 455 042	Cutting Table			1
1/17/37	2 910 401 289	Hex Socket Head Cap Screw		DIN 912-M10x20-12.9	1
1/17/40	3 603 435 056	Set screw			1
1/17/44	1 600 150 013	Spring Washer			1
1/17/46	3 603 391 007	Thread-forming tap. Screw		DIN 7500-UM5x10-ST	1
1/17/49	3 600 109 018	Sealing disk			1
1/17/50	1 601 334 013	Chip Deflector			1
1/20/1/18	2 609 100 650	Switch Slide			1
1/20/1/38	1 607 233 528	Electronic Module			1
1/20/1/41	2 609 131 677	Label			1
1/20/1/48	2 603 490 023	Torx Oval-Head Screw		4x20	1
9	2 609 131 688	Manufacturer's nameplate		LITHEON 12V	1
651	1 607 A35 0C8	Battery Pack	BAT 414 10,8/12V 2,0Ah		1
653	2 607 225 139	Fast Charger	USA/CAN 120/10,8-12V/30 MIN.		1
653	2 607 225 519	Fast Charger	USA 120/3,6-10,8V,1h		1
655	1 907 950 004	Offset Screwdriver		DIN 911, SW3	1
801	2 609 100 773	Housing			1
802	1 607 000 751	DC motor	10,8V		1
808	2 610 006 424	Nameplate			1

Spare parts list

Item	Part Number	Description	Illustration
825	3 607 031 860	Eccentric Shaft	1

Illustration - Type - E

