Repair Parts

RIDGID 4 Gallon Wet/Dry Vac Model Number WD40700/WD4070M0/WD4070EX0

RIDGID parts are available on-line at www.ridgidparts.com

Always order by Part Number - Not by Key Number

▲ WARNING SERVICING OF DOUBLE-INSULATED WET/DRY VAC

In a double-insulated Wet/Dry Vac, two systems of insulation are provided instead of grounding. No grounding means is provided on a double-insulated appliance, nor should a means for grounding be added. Servicing a double-insulated Wet/Dry Vac requires extreme care and knowledge of the system, and should be done only by qualified service personnel. Replacement parts for a double-insulated Wet/Dry Vac must be identical to the parts they replace. Your double-insulated Wet/Dry Vac is marked with the words "DOUBLE INSULATED" and the symbol (square within a square) may also be marked on the appliance.

To reduce the risk of injury from electrical shock, unplug power cord before servicing the electrical parts of the Wet/Dry Vac.

| Key No. | Part No. | Description |
|------------|----------|-----------------|
| 1 | 831388 | Float |
| 2 | 818977-1 | Filter Cage |
| 3 | VF3500 | †Filter |
| 4 | VT1720 | †Hose Assembly |
| 5 | VT1709 | †Utility Nozzle |

| Key No. | Part No. | Description |
|------------|----------|-----------------|
| 6 | VT1781 | †Car Nozzle |
| 7 | VT1708 | †Extension Wand |
| 8 | 820002 | Caster |
| 9 | 831823 | Rear Wheel |
| 10 | SP6732 | Owner's Manual |

† These replacement parts may be available where you purchased your Vac.

